



## ecology and environment, inc.

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415

International Specialists in the Environment

REFERENCE 18

SITE NAME Chem. Recovery System

SITE ID OH D 057001810

147623

### M E M O R A N D U M

DATE: March 24, 1986  
TO: File  
FROM: Pat Petrella  
SUBJECT: Observations at Chemical Recovery System, Inc.  
Site, Elyria, Ohio

On a recent (February 5, 1986) site visit to the subject site, there didn't appear to be any diversion or containment structures for runoff. The site sloped gently toward the river. The river is situated approximately 20' below the level of the road adjacent to a steep (approximately 45%) slope. I'd estimate the site slope to be a drop of about 2 feet in 250' (the approximate width of the facility).

85X:4W